

Engine Liner Mapping

Next Generation Engine Liner Measurements for marine 2-stroke engines

02nd March 2021 – Hamburg

Presentation by Birk Fleischer – CTO – Tenaro GmbH Hamburg, Germany




Engine Liner Mapping

- Method for engine liner internal surface inspection
 - In-situ, hot engine "required"
 - ► 2-stroke scav. ports required
 - ► 400+ mm bore size
 - Execution requires one engine stroke

- Combination of
 - On-site attendance and data gathering
 - Data verification
 - Data processing and post-processing
 - Reporting and recommendations

On-site work





4 tools:

- ► Liner wear gauge system
- Liner camera system
- Piston ring coating thickness gauge
- Piston ring camera system
- Use scavenge air ports only
- Move liner up & down one time (~7min)
- ► No engine top side work
- Pre-heated engine
- Contactless, autonomous, precise, fast



Processing

- On-site result
 - ► Abt. 12.000 to 15.000 wear points per liner
 - ► Abt. 1700 MB of liner pictures
 - Abt 200 piston coating readings
 - ► Abt 300 MB of high-resolution ring pictures
- Initial data verification on-site
- Cross-referencing sensor data and calibration information for in-depth data check in office
- Correction for temperature


Results – wear liner & ring coating Quantitative results – 2D – sections & graphs



Cylinder Unit ID 10 1 2 3 4 5 6 7 8 9 11 12 64.790 64.790 64.790 64.790 64.790 64.790 64.790 R-hrs liner wear [mm] Direction 1,38 1,66 1,31 1,12 **0°** 1,06 1,47 1,45 90° 1,42 1,29 1,54 1,69 1,75 1,69 1,40 180° 1,47 1,05 1,59 1,58 1,17 1,48 1,40 270° 1,49 1,28 1,42 1,72 174 1,74 1,32 DATA F-A 2.85 3,25 3.05 2.93 2,29 2.11 2.71 E-M 2,92 2,57 2,96 3,41 3,50 3,44 2,73 INER Ovality -0,07 -0,46 0,29 -0,36 -0,57 -0,73 -0,44 Wear rate [mm/1000 hrs] - Lifetime in Rhrs W-Rate 0,045 0,036 0,048 0,050 0,050 0.047 0,039 35.000 43.000 68.000 31.000 32.000 37.000 59.000 remain. lifetime total lifetime 100.000 96.000 97.000 102.000 124.000 108.000 133.000 $\Theta \bigcirc \Theta$ $\Theta \cup \Theta$ $\Theta \bigcirc \Theta$ Status 000 Position coating thickness [µm] DATA 0 0 23 10 0 0 0 MT 0 0 0 0 0 0 0 RING MB 33 0 0 0 0 0 0 51 0 0 0 0 0 B 0 Recommended liner limits & colour code Piston ring colour code >275µm like new Max wear [0,8% D] 4,80 mm 75% of ma Max. ovality [0,1% D] 0.60 100->275 normal mm High wear rate warning 0.160 mm per 1000Rhrs <100 µm worn <12 µm Low wear rate warning 0,032 mm per 1000Rhrs no coating this colour likely broken Target wear rate (+/- 0.01) mm per 1000Rhrs 0,053 Target Rhrs 90.000 Min, Rhrs 30.000 Max, Rhrs 150.000








System resolution 0.01mm System precision +/- 0.03mm

Results - wear Quantitative results -2D - Trends







Track wear change in full circumference

Results - wear Qualitative results - full surface







Full surface 3D models of liner wear find issues, analyse, understand





Results – liner camera

- Liner: abt 40 pictures per liner
- Detailed pictures of
 - liner wall, lub oil injection area
 - Cylinder cover, Exhaust valves, Fuel injectors
 - Surface coverage with soot/deposits
 - Starting air valve












Results - ring pictures





- Piston rings: abt 12 pictures per piston (3 per ring)
- Surface structure, coating, crown gap
- Crown deposits, optional skirt condition




Results – thermal analysis


- Review of preheating distribution
- Reverse engineering for cooling water distribution
- Predictions on:
 - Liner in-service cooling behaviour
 - Fouling of liners on water side
 - Deposits in upper/lower water jacket













Liner mapping review


More details mean better understanding of wear behaviour

Historical data vs current






► Standard vs current



Reporting & Recommendations



- comprehensive report for all measurements and inspections
- Traffic light system for easy overview
- **Clear recommendations**

The liners show typical wear pattern of a new liner with increased wear in the lower stroke area (yellow arrow). The wear is well within limits. Top stroke area shows local ovality and partial gas leakage. We recommend check the lubrication timing, material and injector function and to monitor the development more closely.

eeee ~ liner L2, L4, L6 & L7

The wear is notably beyond recommended limits, the liners show full gas passage at top piston rings and wear has developed over full stroke. We recommend to exchange the liners soonest.

Cylinder Unit ID		1	2	3	4	5	6	7	8	9
	R-hrs	50.978	50.978	50.978	50.978	50.978	50.978	50.978	50.978	
R DATA	Direction	liner wear [mm]								
	0°	1,09	1,35	1,50	1,23	1,99	1,94	2,63	2,10	
	90°	0,91	0,91	0,99	1,01	1,62	2,12	1,94	1,73	
LINER DATA	180°	0,99	1,15	1,28	0,99	1,81	1,73	2,23	1,78	
	270°	0,97	1,11	1,31	1,25	1,78	1,80	2,22	1,84	
	F-A	2,08	2,49	2,78	2,22	3,79	3,66	4,87	3,88	
	E-M	1,88	2,02	2,30	2,25	3,40	3,91	4,16	3,57	
	Ovality	0,20	0,47	0,48	-0,03	0,39	-0,25	0,71	0,31	
		Wear rate [mm/1000 hrs] - Lifetime in Rhrs								
	W-Rate	0.039	0.044	0.050	0,044	0.071	0,074	0,089	0,073	
	Lifetime	150.000	127.000	106.000	127.000	60.000	55.000	37.000	56.000	
A	Position	coating thickness [µm]								
DATA	Т	58	2	90	470	352	62	271	26	
0	MT	0	0	0	189	84	0	0	0	
RING	MB	2	8	0	194	132	0	10	0	
	В	147	146	197	378	257	216	262	184	



The liner shows wear pattern of a new liner but of slightly irregular shape (green arrow). Wear rate is well within limits, normal monitoring recommended.

~ general impression / summary	
Soot deposits:	high
Carbon deposits:	medium
Lubricator grooves & injectors:	clear & intact
Starting air valve:	clear, no cracks
Exhaust valves:	medium deposits, intact, no pitting
Exhaust valve seats:	not visible
Fuel injectors:	all covered in soot & leaking – overhaul recommended
Wave cut/honing pattern:	none

6. Vi	6. Visual summary									
	Unit	ELM	ELM Trend	PR	PR Trend	CBI-L	CBI-R	Temp		
	1	000	New	000				000		
	2	000		000		00	000	.		
	3	000		000			000			
	4	000		000			000			
	5	000		000			000			
	6	000		000			000			

Alternatives ?






Other methods are slower, less precise and ignore 90% of liner surface

Used when ?

- Maintenance planning (truely condition based)
- Engine budget planning
- Pre-Dock inspections (budgets/work)
- Post purchase inspection
- Engine Problems





Where ?

- ► World wide service also during COVID19
- Local stations:
 - China (Shanghai)
 - Singapore
 - Hamburg (Germany)
 - ► ARA Region
 - Gdansk (Poland)
 - USA (Los Angeles)

- Clustered service:
 - ► Europe
 - ► UAE/Arabia
 - ► Panama
 - ► Houston (US)






Why Tenaro ?

- Maker independent
- Engine service independent
- No selling of spares/overhauls
- Unique cutting edge technology
- Unmatched detail and speed
- Truly world wide service
- Cost effective, low overhead









Engine Liner Mapping (ELM)

Fully electronic system – low on-site work – fast – contactless objective – high precision – high detail – 2D – 3D

ELM allows full understanding of engine condition





ELM – a service to make decisions based on facts not guesstimates







Engine Liner Mapping

Next Generation engine liner measurements for marine 2-stroke engines



Presented by Birk Fleischer CTO/MD

Thank you for joining !

www.tenaro.de
team@tenaro.de
+49 40 822 153 291 (24/7)

https://www.youtube.com/watch?v=zmaK0pKPrks

